

OCS360 Release Notes

Horner Automation has released a new OCS360 revision – OCS360 V3.6.1.90

This is available at the following website: <https://ocs360.cloud>

Versioning information	
OCS360 application	V3.6.1.90

A NOTE ABOUT OCS360 UPDATES:

This update has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application.

New Additions	
1.	Added support for managing subscriptions using OCS360 billing (canceling subscription, updating billing information, adding a payment method, and downloading invoices are supported)
2.	Added voucher support for subscription renewal
3	Added support for monthly subscription plans

Known Issues List		Workaround
1	Register/variable names changed in the program, but in OCS360 widget key name does not change.	When a register/variable name is changed in the program and downloaded to the controller, in OCS360 widgets will stop updating the values. In OCS360 widgets the updated variable name must be selected manually.
2	Switch and Knob control widget images are sometimes not displaying correctly in OCS360	Reload the page by refreshing the browser to display the correct images of widgets
3	The alarm table widget does not have an export widget data option.	None. This is a limitation at this time.
4	Google Map widget showing watermark "development purpose only"	Users can register Google accounts to acquire an API key, then replace the key in the map widget. Use the following link to acquire an API key https://developers.google.com/maps/documentation/embed/get-api-key
5	OCS status register/variable %SR362 not available in IEC programming	Configure OCS360 status variable in MQTT configuration controller dialog.
6	The alarm count widget does not update on new alarm events	This is as per design. The alarm count widget updates when the dashboard loads. Reload the page on the new alarm event
7	A rate limit error occurs when the number of variables published or subscribed is within the subscribed plan limit.	The issue might occur due to clock drift between the OCS and server. To avoid this, it is recommended to keep the publish interval at least one (10 second above the plan limit).

Known Issues List		Workaround
8	Number of simultaneous user login sessions is not as per the subscribed plan limit.	Close the unused log-in session.
10	Some dialogs in OCS360 platform displays text in English even though the platform language is changed.	N/a

Technical Support

North America:

Tel: (317) 916-4274

Fax: (317) 639-4279

Website: <https://hornerautomation.com>

Email: APGUSATechSupport@heapg.com

Europe:

Tel: (+353)-21-4321-266

Fax: (+353)-21-4321826

Website: <http://www.hornerautomation.eu>

Email: technical.support@horner-apg.com